

Link do produktu: <https://sklep.mksservice.pl/c00078700-wiazka-przelacznikow-iskrownika-wire-harnes-with-microswitches-p-39325.html>



## C00078700 - wiązka przełączników iskrownika - wire harnes with microswitches

|                  |                      |
|------------------|----------------------|
| Cena             | <b>70 zł</b>         |
| Dostępność       | <b>Na zamówienie</b> |
| Numer katalogowy | <b>C00078700</b>     |
| Kod producenta   | <b>C00078700</b>     |
| Kod EAN          | <b>8059131787009</b> |
| Producent        | <b>Indesit</b>       |

### Opis produktu

482000027446 / C00078700

Część jest zgodna z dokumentacją urządzeń o kodzie producenta:

|             |             |             |
|-------------|-------------|-------------|
| 03186610100 | 03186610200 | 03216850210 |
| 03216850211 | 03220980000 | 03228850000 |
| 03302700010 | 03302980010 | 25241670110 |
| 25260540010 | 25266740010 | 25294000010 |
| 25294790010 | 25307640210 | 25308490110 |
| 25331080110 | 25331530010 | 25331530110 |
| 25331540410 | 25331590010 | 25336360010 |
| 25336480010 | 25336481210 | 03216850100 |
| 03216880100 | 03294920010 | 25241670000 |
| 25266750010 | 25294770010 | 25302490310 |
| 25302500110 | 25302940010 | 25307510010 |
| 25307590010 | 25308010110 | 25319530110 |
| 25331070010 | 25331080010 | 25331100110 |
| 25331530210 | 25331540310 | 25331570010 |
| 25336481110 | 25339090210 | 25339100210 |
| 03186610000 | 03220980110 | 03231050100 |
| 03237940110 | 03294590010 | 03302660010 |
| 03302690010 | 25241670210 | 25248210000 |
| 25249310110 | 25260500110 | 25265870010 |
| 25268300010 | 25294780010 | 25302490210 |
| 25302500010 | 25302920010 | 25308160010 |
| 25331520310 | 25331540210 | 25331560010 |

|             |             |             |
|-------------|-------------|-------------|
| 25336461010 | 25336481010 | 25339090010 |
| 25339090110 | 25389491010 | 03186660000 |
| 03216850000 | 03216880210 | 03294930010 |
| 03294950010 | 25260480010 | 25260490110 |
| 25260500010 | 25265880010 | 25302470110 |
| 25302730010 | 25302880010 | 25307480010 |
| 25307490110 | 25308060010 | 25308060110 |
| 25319530010 | 25331070110 | 25331070310 |
| 25331080210 | 25331100010 | 25331520010 |
| 25331530310 | 25336451010 | 25336481310 |
| 25339100010 | 25339110010 | 03237930000 |
| 03302670010 | 25241670010 | 25249250010 |
| 25249310210 | 25260480110 | 25293620010 |
| 25301830010 | 25307480110 | 25307640010 |
| 25308010010 | 25308030010 | 25308030210 |
| 25331520510 | 25336460010 | 25336461110 |
| 25359911010 | 25373200010 | 25373261010 |
| 03186610310 | 03292580010 | 25249310010 |
| 25260490010 | 25266730010 | 25294010010 |
| 25302490010 | 25302500210 | 25302710010 |
| 25308030110 | 25308160110 | 25331100210 |
| 25331520110 | 25359921010 | 25373231010 |
| 25389521010 | 03186660310 | 03216880000 |
| 03231050110 | 03293850010 | 25248210010 |
| 25260540110 | 25266720010 | 25302490110 |
| 25302500310 | 25302890010 | 25302910010 |
| 25307490210 | 25307590110 | 25331070210 |
| 25336361010 | 25336451110 | 25339100110 |
| 25339760010 | 25373241010 | 25373251010 |
| 25389491110 | 25389501010 | 25389551010 |
| 03186660100 | 03228850110 | 03237940000 |
| 03294910010 | 25302900010 | 25308110010 |
| 25319530210 | 25331540010 | 25336361110 |
| 25336450010 | 25373190010 | 25389541010 |